

# IloT Tested Devices

Please contact your Genetec Sales representative for device templates

| Manufacturer                        | Product              | Protocol  | Device Firmware               | SC version         | IloT version | Template available | Status*           | Notes   |
|-------------------------------------|----------------------|-----------|-------------------------------|--------------------|--------------|--------------------|-------------------|---|
| Advantech                           | ADAM-6050            | Modbus    | 6.11 B12 / 6.02. B11          | 5.10.2.0 / 5.9.4.0 | 4.4.1        | ✓                  | Tested by Genetec | Template now included with the software package             |
| ALLIGATOR                           | -                    | Modbus    | -                             | -                  | -            | -                  | Tested            | Emergency exit management                                   |
| Allen-Bradley                       | 5069-L340ER          | Modbus    | -                             | -                  | -            | -                  | Tested            | -   |
| AXIS                                | C1410                | MQTT/SNMP | 11.5.64                       | 5.11.3             | 5.0.2        | ✓                  | Tested by Genetec | -   |
| AXIS                                | D3110                | MQTT/SNMP | 11.5.64                       | 5.11.3             | 5.0.2        | ✓                  | Tested by Genetec | -   |
| AXIS                                | D4100-E              | MQTT      | 11.1.72                       | 5.11.1             | 5.0.1        | ✓                  | Tested by Genetec | -   |
| AXIS                                | -                    | MQTT      | -                             | -                  | -            | -                  | Tested            | Remote camera monitoring                                    |
| Bosch                               | FPA-5000             | OPC       | -                             | -                  | -            | -                  | Tested            | -   |
| Bosch                               | AVENAR Panel 2000    | OPC       | 4.2                           | 5.12.1.0           | 5.2.2        | ✓                  | Tested by Genetec | FPA5000 OPC-Server v.2.0.23<br>UaGateway v.1.16.0           |
| Brother                             | DCP-L2550DW          | SNMP      | -                             | -                  | -            | -                  | Tested            | -   |
| Carrier                             | TruVU™ MPC Processor | BACnet    | -                             | -                  | -            | -                  | Tested            | -   |
| Circa (Teletics) / Guardian Telecom | -                    | HTTP      | -                             | -                  | -            | -                  | Tested            | Display camera and location on MAP (Emergency Call Station) |
| COMMEND                             | -                    | HTTP      | -                             | -                  | -            | -                  | Tested            | Display camera and location on MAP (Intercom)               |
| Contemporary Controls               | BASRT-B              | BACnet    | -                             | -                  | -            | -                  | Tested            | Converting BACnet MS/TP to BACnet/IP                        |
| DMP                                 | Fire Panel XR550     | TCP       | 221 with DMP Remote Link 2.31 | 5.12.0.0           | 5.2.0        | ✓                  | Tested by Genetec | -   |

| Manufacturer       | Product   | Protocol | Device Firmware                                    | SC version | IloT version | Template available | Status*           | Notes   |
|--------------------|---|----------|--|------------|--------------|--------------------|-------------------|---|
| Edwards            | EST4  | BACnet   | -  | -          | -            |                    | Tested            | Monitor fire panel  |
| Evolon             | -   | TCP      | 1.1.4  | 5.11.3.4   | 5.0.3        | ✓                  | Tested by Genetec | Template now included with the software package   |
| Flysense           | FS300   | HTTP     | 1.1.0.0  | 5.12.0     | 5.1.0        | ✓                  | Tested by Genetec | -   |
| Genetec            | Streamvault SV-350E iDRAC   | SNMP     | Remote Access Controller 9 v.5.10.00.00 (Build 57) | 5.10.4     | 4.4.2        | ✓                  | Tested by Genetec | -   |
| GUDE               | Expert Power Control 1102   | MQTT     | -  | -          | -            | -                  | Tested            | -   |
| GUDE               | Expert Power Control 1105 with 7105 Temperature and Humidity Sensor | MQTT     | 1.4.1  | 5.11.1     | 5.0.1        | ✓                  | Tested by Genetec | -   |
| HALO               | Smart Sensors models 2C / 3C  | TCP      | 2.11   | 5.12.0     | 5.2.1        | ✓                  | Tested by Genetec | -   |
| Honeywell/Notifier | NFS-320   | BACnet   | -  | -          | -            | -                  | Tested            | Monitor fire panel  |
| Honeywell/Notifier | NFS-640   | TCP      | -  | -          | -            | -                  | Tested            | Monitor fire panel  |
| Incendia           | Pentagone   | MQTT     | 0.15.0   | 5.12.0     | 5.2.1        | ✓                  | Tested by Genetec | -   |
| Inovonics          | Gateway EN7295 Mobile Duress  | MQTT     | 1.4.2  | 5.10.10    | 4.4.171.8    | ✓                  | Tested by Genetec | Tests were made with the following Inovonics equipment: <ul style="list-style-type: none"> <li>• EN7295 Mobile Duress Gateway</li> <li>• EN2233S Mobile Duress pendant</li> <li>• EN5060 Locator</li> </ul> |

| Manufacturer       | Product                            | Protocol             | Device Firmware  | SC version | IIoT version | Template available | Status*           | Notes  |
|--------------------|------------------------------------|----------------------|--|------------|--------------|--------------------|-------------------|--|
| Inovonics          | Gateway EN4080 IP Pendant Solution | BACnet               | 1.4.6.188  | 5.11.1     | 5.0.1        | ✓                  | Tested by Genetec | Tests were made with the following equipment: <ul style="list-style-type: none"> <li>EN1223D Double-Button Water-Resistant Pendant</li> <li>EN1235D Double-Button Belt Clip Pendant</li> </ul> |
| Inveo              | Nano Temp                          | Modbus / MQTT / SNMP | 1.38   | 5.11.3     | 5.0.2        | ✓                  | Tested by Genetec | -  |
| LifeSafety         | Power NL4                          | SNMP                 | 9.77   | 5.11.3     | 5.0.2        | ✓                  | Tested by Genetec | -  |
| Louroe             | LE-870                             | TCP                  | 0.5.2  | 5.12.1     | 5.2.2        | ✓                  | Tested by Genetec | -  |
| Noctuai            | Flare Inspector                    | MQTT                 | -  | -          | -            | -                  | Tested            | -  |
| Panasonic          | Fire Panel EBL512 G3               | OPC                  | 3.0.0 Beta 16 (EBLWEBNLX)  | 5.10.2.0   | 4.4.1        | ✓                  | Tested by Genetec | -  |
| Potter             | Fire Panel AFC-1000                | BACnet / Modbus      | 2.10.679.0 (BACnet link)   | 5.11.3.3   | 5.0.3        | ✓                  | Tested by Genetec | -  |
| Siemens            | PLC 1217C                          | OPC                  | 04.06.00 (1217C CPU)   | 5.11.3.3   | 5.0.3        | ✓                  | Tested by Genetec | -  |
| Siemens            | PLC 1214C                          | OPC                  | -  | -          | -            | ✓                  | Tested by Genetec | -  |
| Stanley Healthcare | HUGS                               | HTTP                 | -  | -          | -            | -                  | Tested            | -  |
| Triton             | 3D Sense                           | HTTP                 | -  | 5.11.1     | 5.0.2        | ✓                  | Tested by Genetec | -  |
| Unitronics         | Samba                              | Modbus               | -  | -          | -            | -                  | Tested            | -  |
| Unitronics         | V130 PLC                           | Modbus               | V130-33-T2(A), O/S: 4.11 (02), BOOT: 2.2(53), FACTORY BOOT: 1.2 (03) | 5.11.1     | 5.0.2        | ✓                  | Tested by Genetec | -  |
| Viper Imaging      | -                                  | OPC                  | -  | -          | -            | -                  | Tested            | Receive alarms from thermal analytic platform  |
| WEG                | Multimeter MMW03                   | Modbus               | -  | -          | -            | -                  | Tested            | -  |

| <b>Manufacturer</b> | <b>Product</b>    | <b>Protocol</b> | <b>Device Firmware</b> | <b>SC version</b> | <b>IloT version</b> | <b>Template available</b> | <b>Status*</b> | <b>Notes</b> |
|---------------------|-------------------|-----------------|------------------------|-------------------|---------------------|---------------------------|----------------|--------------|
| Zenitel             | Vingtor-Stentofon | SNMP            | -                      | -                 | -                   | -                         | Tested         | -            |